



Portable X-ray Flaw Detector

DDGT NDT

Controller




- Over-voltage protection
- Low-voltage protection
- Over-current protection
- Low-current protection
- Over-temperature protection



- Earth Terminal
- Connecting Cable Socket
- Power Cable Socket
- Fuse 2A/5A
- Fuse 20A

Generator



Equipment Configuration

- X-ray Generator
- Controller
- Connecting Cable 25m
- Power Cable 10m
- Earth Wire 5m
- Accessories
- Testing Report
- Instruction Manual
- Transport Case(Optional)



Warranty